

Deer Lake

LAKE HABITAT ASSESSMENT, LAKE VEGETATION IDEX, SUBMERGED VEGETATION SURVEY AND WATER QUALITY

David Eilers, Towfigul Islam Khan | USF Water Institute | July 14, 2025

Methods

STUDY AREA ANALYISIS

The watershed containing the Lake was analyzed using ESRI ArcGIS Pro. Using this software with 2023 ESRI Basemaps aerial, 2020 Land Use/ Land Cover (LULC), Landscape Development Intensity (LDI) Index values were calculated for the 100 meter buffer surrounding the lake following the procedures of FDEP (https://floridadep.gov/dear/bioassessment/content/bioassessment-ldi-hdg-bcg). "The Landscape Development Intensity index (LDI) is an estimate of how much humans have altered an area of interest around a waterbody. Various land use types (low density residential, row crops, industrial, natural) are assigned coefficients of land use intensity based on estimates of the amount of human energy that is put into those land use types. The LDI is calculated by multiplying each land use coefficient by the percentage of the area of interest occupied by that land use and then summing the results. The Florida Department of Environmental Protection (DEP) uses the LDI as a tool to estimate potential land use impacts on streams, lakes, and wetlands. For streams and rivers, DEP typically uses a LDI calculated for the 100 m buffer of the waterbody for 10 km upstream of the point of interest. For lakes and isolated wetlands, DEP typically uses a LDI calculated for the 100 m buffer around the waterbody. LDI values less than two (≤2) can be considered minimally disturbed."

LAKE BATHYMETRY AND MORPHOLOGICAL CHARACTERISTICS ASSESSMENT

The Bathymetric Map[1] provides the lake's morphologic parameters in various units. The bottom of the lake was mapped using a Lowrance Elite 7 Ti Wide Area Augmentation System (WAAS)[2] enabled Global Positioning System (GPS) with Totalscan transducer (bottom sounder) to determine the boat's position, and bottom depth in a single measurement. The result is an estimate of the lake's area, mean and maximum depths, and volume and the creation of a bottom contour map. Besides pointing out the deeper fishing holes in the lake, the morphologic data derived from this part of the assessment can be valuable to overall management of the lake vegetation as well as providing flood storage data for flood models.

[1] A bathymetric map is a map that accurately depicts all of the various depths of a water body. An accurate bathymetric map is important for effective herbicide application and can be an important tool when deciding which form of management is most appropriate for a water body. Lake volumes, hydraulic retention time and carrying capacity are important parts of lake management that require the use of a bathymetric map.

[2] WAAS is a form of differential GPS (DGPS) where data from 25 ground reference stations located in the United States receive GPS signals form GPS satellites in view and retransmit these data to a master control site and then to geostationary satellites. For more information, see end note 2.

LAKE VEGETATION INDEX ASSESSMENT

Hillsborough County requested the implementation of the Florida Department of Environmental Protection methods for Lake Vegetation Index (LVI 1000) (http://www.dep.state.fl.us/water/sas/sop/sops.htm) using forms FD 9000-03 (Physical/Chemical Characterization), FD 9000-06 (Lake Habitat Assessment) FD 9000-27 (LVI Field Sheet) and FD 9000-31 (Lake Observation Field Sheet).

The Lake Vegetation Index (LVI) is a rapid assessment protocol in which selected sections of a lake are assessed for the presence or absence of vegetation through visual observation and through the use of a submerged vegetation sampling tool called a Frodus. The assessment results provide a list of species presents and the dominant and where appropriate co-dominant species that are found in each segment. These results are then entered into a scoring table and a final LVI score is determined. LVI scores provide an estimate of the vegetative health of a lake. Our assessment team was trained and qualified by FDEP to conduct these assessment as an independent team and must prequalify each year prior to conducting additional assessments. The LVI method consists of dividing the lake into twelve pie-shaped segments (see diagram below) and selecting a set of four segments from the twelve to include in the LVI. The assessment team then travels across the segment and identifies all unique species of aquatic plant present in the segment. Additionally, a Frodus is thrown at several points on a single five-meter belt transect that is established in the center of the segment from a point along the shore to a point beyond the submerged vegetation zone. For scoring, the threshold score for impairment is 43.

Four metrics are utilized in the Lake Vegetation Index Survey; Dominant Coefficient of Conservatism (CoC), Percent Florida Exotic Pest Plant Council Type 1 (% FLEPPC), Percent Native Taxa, Percent Sensitive Taxa.

The Dominant Coefficient of Conservatism (CoC) metric for the dominant or co-dominate species in each section. The CoC applies a score of 0-10 to each species based on its ecological tolerances and fidelity to pre-settlement conditions. Species with higher scores show a high fidelity to native, undisturbed habitats and are typically sensitive to alterations. Available CoC scores can be obtained from LT 7000 from the Florida Department of Environmental Protection at: http://www.dep.state.fl.us/water/sas/sop/sops.htm.

The percent FLEPPC (Florida Exotic Pest Plant Council) Category 1 invasive exotic taxa in a single sampling unit (pie slice) by dividing the number of FLEPPC Category I taxa by the total number of taxa in that sampling unit. Multiply result times 100. Refer to Appendix LVI 1000-1 to determine which plants are on the FLEPPC Category 1 list. Note that not all exotic taxa should be included in this metric, only those listed in Appendix LVI 1000-1 as Category 1 FLEPPC. If the FLEPPC updates their list of Category 1 exotics, those updates shall not be reflected in this calculation until they are included in Appendix LVI 1000-1.

The percent native taxa in a single sampling unit (pie slice) is calculated by dividing the number of native taxa by the total number of taxa in that sampling unit. Multiply result times 100. Nativity status is determined by the Plant Atlas from the Institute for Systematic Botany, and is listed in Appendix LVI 1000-1. For informational purposes, visit the website

http://www.florida.plantatlas.usf.edu/. Taxa that are native according to the Plant Atlas from the Institute for Systematic Botany but are not on the list in Appendix LVI 1000-1 may be included in this metric calculation, but inclusion of these additional taxa is not required.

The percent sensitive taxa in a single sampling unit by summing the number of taxa with a C of C (Coefficient of Conservatism) score >= 7 and then dividing by the total number of taxa in that sampling unit. Multiply result times 100. Refer to Appendix LVI 1000-1 for a list of C of C scores.

The collected bathymetric data is analyzed for submerged aquatic vegetation (SAV) calculations including the percentage of the surface area of the lake inhabited by SAV as well as an estimate of the percent volume of the lake inhabited by SAV. SAV is an important component to a lakes nutrient cycling as well as chlorophyll concentrations due to the SAV and phytoplankton competing for available nutrients in the water column. In addition SAV serves a vital role as habitat for many species of macroinvertebrates and fish as well as substrate for epiphytic algae.

WATER QUALITY ASSESSMENT

Physical water quality samples were taken using a Eureka Manta Sub-2 multiprobe pre and post calibrated on the day of the assessment. Measurements taken with this device include: depth, conductivity, pH, Dissolved Oxygen (mg/l and % Saturation) and salinity. Chemical water parameters were collected and preserved on ice by USF Water Institute staff and analyzed at the Hillsborough County Public Utilities Laboratory Analysis include; Chlorophyll (a, b, c, t and corrected), Alkalinity, Color, E Coli, Enterococci, Ammonia, Nitrates/Nitrites, Total Phosphorous, Kjeldahl Nitrogen and Total Nitrogen. The results of the water quality sampling effort will be discussed in the framework of the FDEP Numeric Nutrient Criteria. Due to the lack of public access to the majority of lakes in Hillsborough County, the majority of available water quality samples are from the resident volunteer LAKEWATCH program. This data is being included in the analysis of Hillsborough County lakes.

Study Area

Deer Lake is located in the Coastal Old Tampa Bay Watershed in north western Hillsborough County, Florida. The Landscape Development Intensity Index of the 100 meter buffer around Deer Lake is dominated by residential (72%) and natural (19%) land uses. The resulting LDI value for the 100 meter buffer around Deer Lake is 6.1.

FIGURE 1: 2025 DEER LAKE ASSESSMENT STUDY AREA MAP



Deer Lake
WBID 1536C

Sample Date - July 14, 2025
Surface Area - 35.3 acres (1,536,726 sqft)
100m Landscape Development Intensity - 6.1
Dominant Land Use 100m Buffer -
Residential (72%)
Natural (19%)
Lake Vegetation Index - 45
Water Clarity - 1.45 m (4.76 ft)
Submerged Aquatic Vegetation
Percent Area Covered - 1.08%
Percent Volume Inhabited - 17.91%
SAV Volume - 168,270 cubic feet



Lake Bathymetry and Morphological Characterization

At the time of the assessment, Deer Lake was experiencing normal water levels (63.68 feet NAVD88 on staff gauge) resulting in a 35.3 acre water body. Deer Lake at the time of the assessment had a mean water depth of 10.2 feet and a maximum observed depth of 24.49 feet. The volume at this time was approximately 116,689,565 gallons. Figure 2 shows the resulting bathymetric contour map for Deer Lake from data collected on July 14, 2025.

Table 1: Morphological Calculations for Deer Lake

Parameter	Feet	Meters	Acres	Acre-Ft	Gallons
Surface Area (sq)	1,536,726	142,765	35.3		
Mean Depth	10.2	3.09			
Maximum Depth	24.49	7.46			
Volume (cubic)	15,559,018	441,711		358.1	116,689,565
Gauge (NAVD 88)	63.68	19.41			

Figure 2: 2025 2-Foot Bathymetric Contour Map for Deer Lake






Figure 3 Overview photograph of the typical shoreline of Deer Lake with a shoreline maintained for residential land use often with the removal of shoreline buffer vegetation and abundant Panicum repens.

Lake Habitat and Lake Vegetation Index Assessment

The lake assessment for Deer Lake was conducted on July 14, 2025. The water in Deer Lake was characterized as clear with low turbidity. The secchi disk depth was 1.45 meters (4.76 ft). The vegetation quality of the plants in and buffering Deer Lake are predominantly native species with extensive growths of *Panicum repens.* The percentage of non-native FLEPPC 1 species ranged from 16.0% (region 8) to 23.53% (region 11). Stormwater reaches the lake predominately via ditches, pipes, and surface flow over cultivated vegetation, and there are either ineffective or no BMPs in place. The bottom substrate quality was dominated by sand, coarse particulate organic matter and submersed vegetation. The development along the shoreline has altered the surrounding buffer extensively with 50-70% of the shoreline being residential houses with less than 18 meters of buffer.



Figure 4 The native submersed aquation Vallisneria americana was dominant in region 2 and codominant in regions 5, 8 and 11 of the Lake Vegetation Index on Deer Lake

The Lake Vegetation Index identified 26 species of wetland vegetation growing in the four selected sections along Deer Lake. The majority of these species (19) are native species. The remaining 7 species (*shown in Table 2*) are non- native or invasive to this region. The vegetation community along the shorelines of Deer Lake has been altered by residential housing removing the buffer vegetation. The edges of the lake are dominated by species able to rapidly colonize following the frequent disturbance of mowing, such as *Panicum repens* and emergent aquatics such as T*ypha*. At the time of the assessment the water transparency was 1.45 m (4.76 ft). High annual average secchi disk depths allow for an extensive littoral zone with establishment of floating leaved and submerged aquatic vegetation. Two species of submersed aquatic vegetation were observed during the lake vegetation index, these species include *Eleocharis baldwinii* and *Vallisneria americana*. *Vallisneria americana* was classified as dominant in region 2 and codominant in regions 5, 8 and 11 of the Lake Vegetation Index. The floating leaved vegetation community had 3 species present, including *Nymphaea odorata, Nuphar and Hydrocotyle.*

The calculated LVI score for Deer Lake was 45, above the impairment threshold of 43 indicating the vegetation community is showing evidence of being "Healthy". Figure 5 shows the map of Deer Lake detailing the LVI regions used for the assessment (Regions 2, 5, 8, 11). Table 2 details the species list results of the Lake Vegetation Index. Table 3 details the scoring result for the Lake Vegetation Index.

By analyzing the collected sonar chart, submerged aquatic vegetation potentially covered approximately 17.91% of the surface area of Deer Lake. This submerged vegetation inhabits an estimated 1.08% of the water volume in Deer Lake. The average height of submersed aquatic vegetation was 0.6 ft. Figure 6 shows the results of the SAV analysis indicating the location and height of SAV estimated from collected sonar readings.




Figure 5 Deer Lake Lake Vegetation Index Sampling Map




Figure 6 Deer Lake Sonar Derived Submersed Aquatic Vegetation Map

Table 2: Lake Vegetation Index results for Deer Lake July 14, 2025. In this table, "p" represents the taxa was present in the region while "c" and "d" denotes the taxa as being co-dominant or dominant in the vegetation region.

Taxon	Region				Occurrences	C of C Score	FLEPPC Status	Wetland Status	Nativity
	2	5	8	11					
Blechnum serrulatum			p		1	5.50	Not Listed	FACW	Native
Cinnamomum camphora			p	p	2	0.00	Category 1	UPL	Exotic
Colocasia esculenta	p	p	p	p	4	0.00	Category 1	OBL	Exotic
Cyperus odoratus	p		p	p	3	3.00	Not Listed	FACW	Native
Cyperus polystachyos	p	p	p		3	1.56	Not Listed	FACW	Native
Cyperus surinamensis	p	p	p	p	4	2.03	Not Listed	FACW	Native
Eleocharis baldwinii	p	p	p	p	4	2.82	Not Listed	OBL	Native
Fuirena breviseta			p		1	3.50	Not Listed	OBL	Native
Fuirena scirpoidea	p		p		2	5.50	Not Listed	OBL	Native
Gordonia lasianthus			p		1	7.00	Not Listed	FACW	Native
Hydrocotyle	p	p	p	p	4	2.00	Not Listed	FACW	Native
Ludwigia octovalvis	p		p	p	3	2.00	Not Listed	OBL	Native
Ludwigia peruviana	p		p	p	3	0.00	Category 1	OBL	Exotic
Melaleuca quinquenervia			p	p	2	0.00	Category 1	FAC	Exotic
Mikania scandens	p		p	p	3	1.95	Not Listed		Native
Nuphar			p	p	2	3.50	Not Listed	OBL	Native
Nymphaea odorata	p		p		2	5.00	Not Listed	OBL	Native
Nyssa sylvatica biflora			p		1	7.00	Not Listed	OBL	Native
Panicum repens	p	c	c	c	4	0.00	Category 1	FACW	Exotic
Pontederia cordata			p	p	2	5.38	Not Listed	OBL	Native
Sagittaria lancifolia	p		p		2	3.00	Not Listed	OBL	Native

Taxon	Region				Occurrences	C of C Score	FLEPPC Status	Wetland Status	Nativity
	2	5	8	11					
Schinus terebinthifolius	*p*				*1*	0.00	Category 1	FAC	Exotic
Sphagneticola trilobata	*p*	*p*	*p*	*p*	*4*	0.00	Category 2	FACW	Exotic
Taxodium	*p*	*p*	*p*	*p*	*4*	7.00	Not Listed	OBL	Native
Typha	*p*		*p*	*p*	*3*	1.00	Not Listed	OBL	Native
Vallisneria americana	*d*	*c*	*c*	*c*	*4*	7.00	Not Listed	OBL	Native

Table 3: Scoring Summary for the Lake Vegetation Index

LVI Sample Result:				45
Region	South			
Metric / Section	2	5	8	11
Total # Taxa	18	9	25	17
% Native Taxa	72.22	66.67	76.00	64.71
% FLEPPC 1 Taxa	22.22	22.22	16.00	23.53
% Sensitive Taxa	11.11	22.22	16.00	11.76
Dom Taxa Count	1	2	2	2
CofC Dom Taxa	7.00	3.50	3.50	3.50
Section LVI	50.73	43.98	53.18	32.60

Water Quality Assessment

Limited long-term water quality data is available for Deer Lake. The available data was collected by Lakewatch, and Hillsborough County Environmental Services. Table 4 provides a summary of the Physical/Chemical conditions recorded at the middle of Deer Lake during the University of South Florida/ Hillsborough County Environmental Services assessment in 2025.

Table 4: Deer Lake Water Quality 7/14/2025 (Field)

Meter Readings:	Depth m	Temp (°C)	pH (SU)	D.O (mg/L)	D.O Sat. (%)	Cond. (µMho/cm)	Salinity (ppt)
Top:	0.5	31.2	7.21	7.65	104	148.4	0.07
Mid-Depth:	2.25	31.2	7.09	6.49	88.5	148.6	0.07
Bottom:	3.52	29.8	7.22	6.25	82.5	149.2	0.07

The chemical water quality analysis for Deer Lake is shown in Table 5. These values are the geometric mean value of available data for each annual period as well as the period of record. The FDEP Numeric Nutrient Criteria splits lakes into separate types based on color at 40 PCU. The "clear" water lakes below this value are further split into alkaline and acidic based on an alkalinity value of 20 mg/L $CaCO_3$. The long term color and alkalinity data are insufficient to accurately classify the lake, as such the remaining discussion will be utilizing the available data. The long term color data have a geometric mean value of 14.1 PCU, classifying it as a clear water lake (less than 40 PCU). Total Alkalinity period of record geometric mean value is not available. Specific conductance values can substitute for alkalinity data. The specific conductance data indicates that Deer Lake would be classified as an alkaline lake. The NNC thresholds for a clear-alkaline lake with insufficient data to calculate NNC (Previous three years with at least 4 samples per year in separate seasons) are 20 µg/L for Chlorophyll-a Corrected for Phaeophytin, 0.03 mg/L for Total Phosphorous and 1.05 mg/L for Total Nitrogen. This analysis will use the limited data available to discuss values in terms of numeric nutrient criteria although there is insufficient data to do so.

Geometric mean Chlorophyll-a corrected values for the past three years are below the threshold with annual geometric means of 6.2 µg/L (2022), 2.8 µg/L (2023) and No Data (2024). The 2025 geometric mean was 12.8 µg/L. The period of record geometric mean for chlorophyll-a corrected is 5.3 µg/L.

Total Phosphorous geometric mean values for the most recent data were below the nutrient threshold for clear-alkaline lakes in the peninsula region with insufficient data with a value of 0.021 mg/l (2022), 0.024 mg/L (2023) and No Data mg/L (2024). The 2025 geometric mean was qualified as <0.068 mg/L. The period of record geometric mean for total phosphorous is 0.013 mg/L.

Total Nitrogen values were below the nutrient threshold for clear-alkaline lakes with insufficient data with a value of 0.700 mg/l (2022), 0.670 mg/L (2023) and No Data (2024). The 2025 geometric mean was 0.750 mg/L. The period of record geometric mean for total nitrogen is 0.550 mg/L.

Table 6 includes this data in the numeric nutrient criteria framework using the data from this assessment and the previous 3 years of data collected by Hillsborough County and Lakewatch.

Bacteria testing showed low levels of E. Coli (17.88 colonies/100ml) and low levels of Enterococci (50.6 colonies/100ml) exceeding the rules set forth in FDEP 62-302.530 (https://www.flrules.org/gateway/RuleNo.asp?title=SURFACE%20WATER%20QUALITY%20STANDARDS&ID=62-302.500) "Most Probable Number (MPN) or Membrane Filter (MF) counts shall not exceed a monthly average of 200, nor exceed 400 in 10% of the samples, nor exceed 800 on any one day. Monthly averages shall be expressed as geometric means based on a minimum of 10 samples taken over a 30 day period."

Table 5: Deer Lake FDEP, Lakewatch and Hillsborough County Environmental Services Water Quality Results Laboratory Results

Parameter	2022	2023	2024	POR Mean Value	Units
Alkalinity	No Data	No Data	No Data	No Data	**mg/LCaCO3**
Color	No Data	No Data	No Data	14.1	**PCU**
E Coli	No Data	No Data	No Data	17.88	**#/100ml**
Enterococci	No Data	No Data	No Data	50.6	**#/100 ml**
Chlorophyll a	9.3	3.8	No Data	5.1	**ug/L**
Chlorophyll b	No Data	No Data	No Data	3.1	**ug/L**
Chlorophyll c	No Data	No Data	No Data	3.7	**ug/L**
Chlorophyll a Corrected	6.2	2.8	No Data	5.3	**ug/L**
Ammonia	No Data	No Data	No Data	<0.073	**mg/L**
Nitrates/Nitrites	No Data	No Data	No Data	<0.043	**mg/L**
Kjeldahl Nitrogen	No Data	No Data	No Data	0.745	**mg/L**
Total Nitrogen	0.700	0.670	No Data	0.550	**mg/L**
Total Phosphorus	0.021	0.024	No Data	0.013	**mg/L**

Table 6: Numeric Nutrient Criteria Framework

Parameter	Value
Geometric Mean Color (pcu)	14.1
Number of Samples	15
Specific Conductance	147.81
Number of Samples	18
Lake Type	Clear-Alkaline

Year (# of Samples)	Geomean Chla Corrected (µg/L)	Chlorophyll a Criteria (µg/L)	Geomean Total Phosphorous (mg/L)	Total Phosphorous Criteria (mg/L)	Geomean Total Nitrogen (mg/L)	Total Nitrogen Criteria (mg/L)
2022 (4)	6.2	< 20	0.021	< 0.03	0.700	< 1.05
2023 (2)	2.8	< 20	0.024	< 0.03	0.670	< 1.05
2024(0)	No Data	< 20	No Data	< 0.03	No Data	< 1.05

Conclusion

Deer Lake is a predominately residential lake in the Coastal Old Tampa Bay Watershed of Hillsborough County, Florida. The results of the assessment of Deer Lake shows a potentially healthy lake based on available Chlorophyll-a, Total Nitrogen and Total Phosphorous concentrations according to the FDEP numeric nutrient criteria using a combination of Lakewatch and Hillsborough County Environmental Services datasets for the past three years, however data is insufficient to formally calculate numeric nutrient criteria.

The system does not show impairment in the vegetation communities according to the Lake Vegetation Index with few invasive species (7) and an overall LVI score of 45. The dominant species of vegetation were *Panicum repens* and *Vallisneria americana*. However, the disturbance to the buffer zone of Deer Lake has resulted in low overall taxa. The assessment revealed a submerged aquatic vegetation community comprising 2 species currently occupying only 17.91% of the surface area and 1.08% of the volume of Deer Lake.