

ENVIRONMENTAL PROTECTION COMMISSION OF HILLSBOROUGH COUNTY

HRS Laboratory Certification #E44057

1900 9th Ave.
Tampa, Fla. 33605
Ph: 272-5960

WATER QUALITY REPORT

sample taken by: G. Toussley	collection date - time: 9-21-88 1330	sampling depth grab
---------------------------------	---	------------------------

Location description: # 809113 Central Place on the Lake (Boat) #1180
- sample taken from boat lake 1st. off old fishing dock. See map.

reason for sampling: Possible pollution problem

Parameter	Unit	Method	Value

Parameter	Unit	Method	Value
COLI MF	#/100ml	31501	56
FECAL COLI MF	#/100ml	31616	52
FECAL STREP MF	#/100ml	31673	56
FC/FS	#	RATIO	.93

Comments: Ratio indicates contamination from mixed sources.

J = Estimated value
K = Actual value less than value given
L = Actual value greater than value given
D = Field measurement


report prepared by: N. Roy	date: 9-26-88
-------------------------------	------------------

lab supervisor: F. Olszewski F. Olszewski
--

HILLSBOROUGH COUNTY
ENVIRONMENTAL PROTECTION COMMISSION

3

Sampling Location Map



Sample Collector

Gerald Tausley

Date

9-21-88